

Compressor Windings, CSR Terminals

Category: Refrigeration

written by www.mbsmpro.com | December 31, 2025



Mbsmpro.com, Compressor, CSR terminals, Common Start Run, PTC relay, overload, start and run capacitor wiring, PSC CSIR CSR motors, multimeter ohm testing

Compressor Windings, CSR Terminals, and Start Devices: Practical Guide for Technicians

Single-phase hermetic compressors use three terminals - **Common (C)**, **Start (S)**, and **Run (R)** - and a combination of overload, relay, and capacitor to start and run safely. Correctly interpreting CSR pin configuration and wiring the starting devices is critical for reliable refrigeration service work and for avoiding repeated compressor burn-outs.

Understanding C, S, and R terminals

On most refrigeration compressors, the three pins form either a triangle or a straight line, and each pin connects to one or both motor windings inside the shell. When the original diagram is missing, technicians can still identify each terminal by measuring resistance with a digital multimeter.

Typical resistance relationships

Measurement pair	Identification rule	Typical range*
C-R	Run winding (lowest resistance)	About 1-5 Ω on small fractional-HP units.
C-S	Start winding (medium resistance)	Usually 3-11 Ω , often 3-5 times C-R.
S-R	Start + run (highest resistance)	Equals C-S + C-R by ohm's law.

*Values vary by model; always compare with the manufacturer's data sheet when available.

To confirm readings, many trainers recommend writing each resistance value on a sketch of the pin layout and checking that the highest reading equals the sum of the other two. If the numbers do not add up, the compressor may have an open winding or internal damage.

CSR, RSIR, CSIR and PSC motor concepts

Single-phase hermetic motors are classified by how capacitors and relays are used with start and run windings. The most common arrangements in light commercial refrigeration

are **RSIR**, **PSC**, **CSIR** and **CSR**, each with different starting torque and component requirements.

Motor types and starting characteristics

Motor type	Components	Typical use case	Starting torque
RSIR (Resistance Start Induction Run)	Start relay + start winding, no capacitor	Small domestic refrigerators, low starting torque.	Low
PSC (Permanent Split Capacitor)	Run capacitor in series with start winding	Smooth, efficient operation, good for low starting load.	Low-medium
CSIR (Capacitor Start Induction Run)	Start capacitor + relay, start winding only during start	Higher torque for larger compressors up to $\approx 3/4$ HP.	High
CSR (Capacitor Start Capacitor Run)	Start capacitor + run capacitor + potential or current relay	Very high starting torque for hard-start conditions.	Very high

CSR systems keep a smaller run capacitor in the circuit after startup to improve power factor and running efficiency while the start capacitor is removed by the relay. These motors are common in high-starting-torque (HST) versions of commercial compressors where frequent cycling and high condensing pressures are expected.

Overload, PTC relay, and run capacitor wiring

The start device assembly brings together three safety-critical components: thermal overload, relay (or PTC), and capacitor. Correct wiring ensures that line voltage reaches the run winding continuously, energizes the start winding only during startup, and disconnects the compressor when overcurrent or overheating occurs.

Typical PTC / solid-state relay and overload wiring (120-240 V)

Step	Connection	Function
1	Line (L) feeds the overload protector, which then connects to C	Overload opens on excessive current or shell temperature.
2	Solid-state relay/PTC connects between C and S with start capacitor in series if CSIR/CSR	Provides high initial current to start winding, then increases resistance and drops out.
3	Line (L) also connects directly to R through the control circuit (thermostat, contactor)	Supplies continuous voltage to run winding during operation.
4	Run capacitor connects between S and R in PSC and CSR systems	Improves running efficiency and torque.

Before wiring, technicians should verify that the overload has less than 1Ω resistance when cold and that the relay coil or PTC element shows the manufacturer's specified resistance range. Any signs of arcing, discoloration or cracked housings are reasons to replace the start device rather than re-use it.

Multimeter checks and safety best practices

Accurate *ohm* measurements and ground tests are indispensable when diagnosing compressor failures or confirming correct CSR identification. At the same time, technicians must follow lock-out/tag-out procedures and respect the refrigeration system's pressure hazards.

Recommended testing workflow

1. Isolate and discharge

- Disconnect power, verify zero voltage, and discharge capacitors before touching any terminals.

2. Ohm the windings

- Measure all three combinations (C-R, C-S, S-R), verify the add-up rule, and compare with catalog ohm ranges when available.

3. Check for shorts to ground

- Use the highest megohm setting to test between each terminal and the shell; any measurable continuity usually means the compressor is grounded and must be replaced.

4. Verify start components

- Measure overload resistance ($<1\ \Omega$ closed) and relay / PTC resistance (3-26 Ω typical on many plug-in designs), and confirm capacitors with a capacitance meter.

5. Monitor running amperage

- After re-wiring, compare running current with the nameplate RLA or data-sheet values; high amps may signal improper capacitor size, high head pressure or internal mechanical problems.

COMPRESSOR WINDINGS AND PIN CONFIGURATION

C = COMMON


S = START

R = RUN

START WINDINGS - **C** TO **S** = 3Ω to 11Ω

RUN WINDINGS - **C** TO **R** = 1Ω to 5Ω



ELECTRICAL CONNECTIONS ON COMPRESSOR



START DEVICE



RELAY / OVERLOAD SOLID STATE (PTC)



UMM-MEASUREMENTS

OVERLOAD, FRONT TO BACK LESS THAN 1 OHM OR CLOSED
RELAY - "S" 1Ω "R" - 3 to 26 OHMS

Andrea Julia



tecumseh-service-handbook_na_enDownload

Andrea Julia configuration

Compressor windings, terminal pin configuration, and the start components used in a refrigerator or air-conditioning compressor.

1. Compressor Windings and Terminals

A single-phase compressor has three terminals:

- C (Common)
- S (Start)
- R (Run)

These three pins can be arranged in different physical positions, but their electrical function is the same.

Winding Resistance Values (Typical)

Measured using a multimeter (Ohms Ω):

- C to S (Start winding): $3 \Omega - 11 \Omega$
- C to R (Run winding): $1 \Omega - 5 \Omega$
- S to R = Start + Run (highest resistance)

👉 The Start winding always has higher resistance than the Run winding.

2. Electrical Connection on the Compressor

The diagram shows two possible layouts of the compressor pins.

Even if the position changes, the labels C, S, and R must be identified correctly before wiring.

3. Start Device Assembly

The start system usually consists of:

- PTC Relay (Solid State Relay)
- Overload Protector
- Run Capacitor (if used)

Functions:

- PTC Relay:
 - Temporarily connects the Start winding during startup.
 - Disconnects it automatically once the compressor is running.
- Overload Protector:
 - Protects the compressor from overheating or overcurrent.
 - Opens the circuit if temperature or current is too high.
- Run Capacitor (optional on some models):
 - Improves efficiency and torque during operation.

4. Multimeter Testing (Shown in Image)

Overload Test:

- Measure front to back
- Reading should be less than 1Ω (closed circuit)

Relay Test:

- Measure between S and R
- Normal reading: $3 \Omega - 26 \Omega$

Abnormal readings indicate a faulty relay or overload.

5. Power Supply

- The diagram shows 120 VAC input going through:

- Overload → Relay → Compressor terminals

6. Internal Relay View

The bottom-right images show the internal structure of the relay, helping identify contacts and working condition.

See less