TH271-FS-316 compressor replacement R134a 1/5 HP LBP specs Embraco EGU 90HLP Tecumseh CDR3545Z field-tested COP metrics technician guide

Category: Refrigeration
written by www.mbsmpro.com | February 11, 2026

Replacing a TH271-FS-316 compressor demands precision you won’t find in generic manuals. This field-tested guide details verified specs, COP performance across evaporating temps, and 10+ compatible replacements. I’ve seen too many technicians skip oil compatibility checks—let’s fix that today.