

# 1/5 HP Compressor oil change: How much and how to do it right

**Site:** Mbsmpro

**Date:** April 13, 2026 | **Author:** www.mbsmpro.com

**URL:** <https://mbsmpro.com/1-5-hp-compressor-oil-change-how-much-and-how-to-do-it-right/>



## Professional Commentary (The Spirit of the Craft)

“When we talk about a **1/5 HP compressor**, we are essentially talking about the ‘heart’ of a domestic refrigerator or a small cooler. In this field, the fine details are what set a professional apart:


- **The Quantity:** Typically, this size requires about **200 to 250 ml** (depending on the model and manufacturer, such as Danfoss or Jiaxipera). The golden rule here is ‘precision by the milliliter.’ Excess oil can lead to **‘Oil Logging’** within the cooling circuit, while a deficit causes friction that eventually kills the compressor.
- **The Method:** It’s not just about pouring oil; it’s a matter of **integrity**. You must ensure the old oil is completely drained while inspecting it for impurities. If the oil is black or has a burnt odor, it’s a clear diagnostic sign of the motor’s condition. As for recharging, it must be done via the service line using **vacuum suction** to ensure no moisture or air enters the system—moisture is the ultimate enemy of refrigeration oil.
- **The Oil Type:** This is the trap! The oil must be selected based on the refrigerant type. For instance, **R134a** requires synthetic **POE oil**, whereas older models or those running on **R600a** may require different specifications.

**A final word:** Someone asking about the ‘quantity and method’ is a technician who respects their craft and aims for perfection, not just someone trying to ‘get the job done.’”









## Latest Articles

- [Guide de Dépannage de la Carte Inverter : Climatiseur Kolin KSM-IW20WAE](#)
- [RCFF-2HP Capillary Tube for a Samsung 18000 BTU air conditioner](#)
- [Carbon brushes washing machine motors](#)
- [Chauffe-eau Junkers : Restauration d'un Classique](#)
- [WS57H Compressor, 1/6 hp, Capacitor Requirement 4mf](#)
- [Hisense inverter expert, installtion](#)
- [Copeland D3DS5-100X 10 HP Freezer Compressor](#)
- [Bitzer 6G-30.2Y: The High-Performance 30 HP Semi-Hermetic](#)
- [Réparer un chauffe-eau à gaz Olympic 6L](#)
- [Best piping practices for semi-hermetic systems](#)

- Core ChauffeEau Junkers Mid-1980s to Late 1990s
- Not recommended R410A to R407c
- Details of refrigerant R134a
- The electrical circuit for a timer-based steam refrigerator is an interesting one
- Changing Filter 1/5 Hp
- 1/5 HP Compressor oil change: How much and how to do it right
- Deep cleaning AC units from A to Z... that's our craft
- Plumbing Fittings Explained
- Can the GL80 compressor be installed in place of the GL90?
- The process of replacing the air conditioner compressor is successful, and it is working as it was before ?