

Carbon brushes washing machine motors

Site: Mbsmpro

Date: May 25, 2026 | **Author:** www.mbsmpro.com

URL: <https://mbsmpro.com/carbon-brushes-washing-machine-motors/>



They are arranged by model and orientation:

- **Left Column (Black holders):** Standard rectangular plastic housings, likely 5mm x 13.5mm or similar common dimensions. Notice

the “**L**” (**Left**) and “**R**” (**Right**) orientations molded into the plastic casings near the bottom of that row, which ensure proper contact angle with the armature.

- **Top Right Column (Black slim holders):** A different mounting design, featuring a centered screw tab and a distinct terminal connection layout.
- **Bottom Right Column (Green holders):** Typically associated with specific motor manufacturers (such as **Ceset** or **Sole** motors frequently used in European washing machines).

Common Technical Specifications to Verify

When replacing or cataloging these parts, you generally look for:

Parameter	Description
Dimensions	Thickness \times Width \times Length of the carbon stick (e.g., $5 \times 13.5 \times 35$ mm or $5 \times 12.5 \times 36$ mm).
Angle	The bevel angle at the tip of the carbon where it meets the commutator.
Casing Type	The configuration of the plastic holder, placement of the mounting pins/holes, and the type of electrical terminal (4.8mm or 6.3mm spade).



Carbon brushes washing machine motors mbsmpro

Latest Articles

- [Guide de Dépannage de la Carte Inverter : Climatiseur Kolin KSM-IW20WAE](#)
- [RCFF-2HP Capillary Tube for a Samsung 18000 BTU air conditioner](#)
- [Carbon brushes washing machine motors](#)
- [Chauffe-eau Junkers : Restauration d'un Classique](#)
- [WS57H Compressor, 1/6 hp, Capacitor Requirement 4mf](#)
- [Hisense inverter expert, installtion](#)
- [Copeland D3DS5-100X 10 HP Freezer Compressor](#)
- [Bitzer 6G-30.2Y: The High-Performance 30 HP Semi-Hermetic](#)
- [Réparer un chauffe-eau à gaz Olympic 6L](#)
- [Best piping practices for semi-hermetic systems](#)
- [Core ChauffeEau Junkers Mid-1980s to Late 1990s](#)

- Not recommended R410A to R407c
- Details of refrigerant R134a
- The electrical circuit for a timer-based steam refrigerator is an interesting one
- Changing Filter 1/5 Hp
- 1/5 HP Compressor oil change: How much and how to do it right
- Deep cleaning AC units from A to Z... that's our craft
- Plumbing Fittings Explained
- Can the GL80 compressor be installed in place of the GL90?
- The process of replacing the air conditioner compressor is successful, and it is working as it was before ?