

Start Run Capacitor Failure, Causes

Category: Mbsmpro

written by www.mbsmpro.com | January 4, 2026



An AC motor run capacitor such as the CBB65 SH usually explodes when it is forced to work beyond its electrical or thermal limits, or when the start-assist components fail and leave it in the circuit too long. This overstress breaks down the dielectric, creates internal gas and pressure, and finally ruptures the can.