

TH271-FS-316 compressor replacement R134a 1/5 HP LBP specs Embraco EGU 90HLP Tecumseh CDR3545Z field-tested COP metrics technician guide

Category: Refrigeration

written by www.mbsmpro.com | February 11, 2026



Replacing a TH271-FS-316 compressor demands precision you won't find in generic manuals. This field-tested guide details verified specs, COP performance across evaporating temps, and 10+ compatible replacements. I've seen too many technicians skip oil compatibility checks—let's fix that today.

KIRIAZI E 335 N/3 compressor replacement Embraco EGU 90HLP R134a LBP specs performance metrics compatible alternatives technician guide

Category: Refrigeration

written by www.mbsmpro.com | February 11, 2026



Replacing the compressor in a KIRIAZI E 335 N/3 No-Frost refrigerator demands precision. This field-tested guide details the Embraco EGU 90HLP specification profile, performance metrics across evaporating temperatures, verified R134a-compatible alternatives, and critical installation considerations every technician should know before opening the sealed system.