

# GMCC PE75H1C Compressor 1/4 HP R134a LBP

**Site:** Mbsmpro

**Date:** January 18, 2026 | **Author:** www.mbsmpro.com

**URL:** <https://mbsmpro.com/gmcc-pe75h1c-compressor-1-4-hp-r134a-lbp/>



**Focus keyphrase:** GMCC PE75H1C Compressor 1/4 HP R134a LBP

Technical Specifications Wiring Diagram and Replacement Cross-Reference

Guide

**SEO title:** Mbsmpro.com, Compressor, GMCC, PE75H1C, 1/4 hp, R134a, 185 W, 1.2 A, 1Ph 220-240V 50Hz, LBP, RSIR, -35°C to -10°C, freezing

**Meta description:** Professional technical analysis of the GMCC PE75H1C compressor. High-efficiency 1/4 HP LBP unit for R134a refrigeration. View wiring schemas, performance tables, and compatible replacements.

**Slug:** gmcc-pe75h1c-compressor-r134a-1-4-hp-lbp-specs

**Tags:** Mbsmgroup, Mbsm.pro, mbsmpro.com, mbsm, GMCC, PE75H1C, R134a, 1/4 HP, LBP, Refrigerator Compressor, HVAC, GL90AA, EMT6170Z, FFI7.5HAK, NL7F, NTU170MT, HMK12AA, HTK12AA, HYB12MHU, NT1114Y

**Excerpt:** The GMCC PE75H1C is a robust hermetic reciprocating compressor engineered for low back pressure applications using R134a refrigerant. Operating at 220-240V 50Hz, this 1/4 HP motor provides a cooling capacity of approximately 185W. This article provides technical datasheets, electrical wiring schemas, and professional cross-reference guides for global refrigeration maintenance and engineering.

---

# Engineering Excellence: The GMCC PE75H1C Hermetic Compressor for R134a Systems

In the world of thermal management and domestic refrigeration, the GMCC PE75H1C stands as a benchmark for reliability and volumetric efficiency.

Manufactured by Anhui Meizhi Compressor Co., Ltd (a Midea Group venture), this unit is a staple in high-performance household refrigerators and chest freezers. As an engineer who has worked extensively on the field, I can attest that the “PE” series represents a balance between compact mechanical design and thermal endurance.

This compressor is designed for Low Back Pressure (LBP) cycles, making it ideal for freezing applications where evaporation temperatures drop significantly below zero. Utilizing R134a, it remains a common choice for technicians servicing existing infrastructure where synthetic oils are standard.

## Detailed Technical Specifications

| Feature                           | Specification                          |
|-----------------------------------|--|
| <b>Model</b>                      | PE75H1C                                |
| <b>Utilisation (mbp/hbp/lbp)</b>  | LBP (Low Back Pressure)                |
| <b>Domaine (Freezing/Cooling)</b> | Freezing / Deep Cold                   |
| <b>Oil Type and quantity</b>      | POE (Ester Oil) - Approx. 180 ml       |
| <b>Horsepower (HP)</b>            | 1/4 HP                                 |
| <b>Refrigerant Type</b>           | R134a                                  |
| <b>Power Supply</b>               | 220-240V ~ 50Hz / 1 Phase              |
| <b>Cooling Capacity BTU</b>       | 631 BTU/h (approx. 185W)               |
| <b>Motor Type</b>                 | RSIR (Resistive Start - Inductive Run) |

|                                |   |
|--------------------------------|---|
| <b>Displacement</b>            | 7.5 cm <sup>3</sup>                           |
| <b>Winding Material</b>        | High-Grade Copper                             |
| <b>Pressure Charge</b>         | 0.8 to 1.3 Bar (Low side)                     |
| <b>Capillary</b>               | 0.031" or 0.8mm ID                            |
| <b>Refrigerator Models</b>     | Midea, Toshiba, Samsung, various local brands |
| <b>Temperature function</b>    | -35°C to -10°C                                |
| <b>With fan or no</b>          | Static Cooling (No fan required)              |
| <b>Commercial or no</b>        | Domestic / Light Commercial                   |
| <b>Amperage in function</b>    | 0.9 A to 1.2 A                                |
| <b>LRA (Locked Rotor Amps)</b> | 11.0 A  |
| <b>Type of relay</b>           | PTC Starter                                   |
| <b>Capacitor or no</b>         | No (Standard RSIR)                            |

## Electrical Wiring Schema (RSIR Logic)

For field technicians, identifying the terminal pins is critical to prevent accidental motor burnout. The GMCC PE75H1C follows the standard triangular layout:

1. **C (Common):** The apex pin. Connected to the line voltage through the internal Thermal Overload Protector.
2. **M (Main/Run):** Bottom-right pin. Connected to the Neutral line.
3. **S (Start):** Bottom-left pin. Connected via the PTC (Positive Temperature Coefficient) relay.

**Operational Logic:** Upon startup, the PTC relay allows current to flow to the Start winding. As the PTC heats up, its resistance increases dramatically, effectively cutting off the Start winding once the motor reaches sufficient RPM, leaving only the Main winding energized.

---

## Performance Comparison: GMCC PE75H1C vs. Industry Standards

When comparing the PE75H1C to other compressors in the same class, we look at the Coefficient of Performance (COP) and displacement efficiency.

| Metric                  | GMCC PE75H1C<br>(R134a) | Equivalent R600a<br>Model |
|-------------------------|-------------------------|---------------------------|
| <b>Gas Displacement</b> | 7.5 cm <sup>3</sup>     | 11.2 cm <sup>3</sup>      |
| <b>Efficiency (W/W)</b> | 1.25                    | 1.45                      |
| <b>Charge Weight</b>    | Standard (120g - 150g)  | Low (40g - 60g)           |
| <b>Pressure Delta</b>   | Moderate                | Low                       |

## Professional Replacement Cross-Reference

Choosing the right replacement is vital for maintaining the refrigerator's original thermal balance.

### 5 Compressor replacements in same value (R134a):

1. **Zem/ACC:** GL90AA
2. **Embraco:** EMT6170Z or FFI 7.5HAK

3. **Secop (Danfoss):** NL7F
4. **Huayi:** AE1380Y
5. **Tecumseh:** THB1375YSS

## 5 Compressor replacements in same value (R600a Conversion):

*Notice: Conversion requires a full system flush and capillary adjustment.*

1. **TEE:** NTU170MT
  2. **Cubigel:** HMK12AA
  3. **Secop:** HTK12AA
  4. **Huayi:** HYB12MHU
  5. **Jiaxipera:** NT1114Y
- 

## Engineering Advice and Best Practices

- **Thermal Protection:** The “Thermally Protected” label indicates an internal bimetallic switch. If the compressor stops and feels extremely hot, do not force a restart. Let it cool for 30 minutes. Check the condenser coils for dust; poor airflow is the primary killer of the PE75H1C.
- **Oil Compatibility:** This unit uses POE (Polyolester) oil. Never mix mineral oil (MO) with this system. If you are retrofitting, ensure the system is flushed with nitrogen to remove moisture, as POE oil is highly hygroscopic.
- **Vacuum Standards:** For R134a systems, reaching a vacuum of at least 500 microns is non-negotiable. Residual moisture reacts with R134a and POE oil to create acid, which will eventually dissolve the copper windings.

- **Startup Amperage:** If the compressor draws high amperage (above 5A) and trips the protector, first replace the PTC relay. These components degrade over time and are a common point of failure before the motor itself fails.

## Benefits of the GMCC PE75H1C

The primary benefit of this model is its durability in tropical climates. The motor is wound with high-quality copper that resists heat better than aluminum alternatives. Its compact footprint also makes it versatile for a wide range of refrigerator brands, simplifying inventory for HVAC professionals.



GMCC PE75H1C Compressor 1/4 HP R134a LBP mbsmpro

## Latest Articles

- [Guide de Dépannage de la Carte Inverter : Climatiseur Kolin KSM-IW20WAE](#)
- [RCFF-2HP Capillary Tube for a Samsung 18000 BTU air conditioner](#)
- [Carbon brushes washing machine motors](#)
- [Chauffe-eau Junkers : Restauration d'un Classique](#)
- [WS57H Compressor, 1/6 hp, Capacitor Requirement 4mf](#)
- [Hisense inverter expert, installtion](#)
- [Copeland D3DS5-100X 10 HP Freezer Compressor](#)
- [Bitzer 6G-30.2Y: The High-Performance 30 HP Semi-Hermetic](#)
- [Réparer un chauffe-eau à gaz Olympic 6L](#)
- [Best piping practices for semi-hermetic systems](#)
- [Core ChauffeEau Junkers Mid-1980s to Late 1990s](#)
- [Not recommended R410A to R407c](#)
- [Details of refrigerant R134a](#)
- [The electrical circuit for a timer-based steam refrigerator is an interesting one](#)
- [Changing Filter 1/5 Hp](#)
- [1/5 HP Compressor oil change: How much and how to do it right](#)
- [Deep cleaning AC units from A to Z... that's our craft](#)
- [Plumbing Fittings Explained](#)
- [Can the GL80 compressor be installed in place of the GL90?](#)
- [The process of replacing the air conditioner compressor is successful, and it is working as it was before ?](#)