

Secop ES7FT.4 Compressor 1/5 HP R134a Technical Specifications and Replacements

Site: Mbsmpro

Date: February 2, 2026 | **Author:** www.mbsmpro.com

URL: <https://mbsmpro.com/secop-es7ft-4-compressor-1-5-hp-r134a-technical-specifications-and-replacements/>



**Mbsmpro.com, Compressor, ES7FT.4, 1/5 hp,
Secop, Cooling, R134a, 147 W, 1.1 A, 1Ph
220-240V 50Hz, LBP, RSIR, –35°C to –10°C, Static
Cooling**

The **Secop ES7FT.4** represents a pinnacle of energy-optimized engineering for tropical refrigeration environments. Designed specifically for low back pressure (LBP) applications, this hermetic reciprocating compressor is a reliable workhorse for household refrigerators and small commercial freezers. Operating on **R134a** refrigerant, it balances thermal efficiency with the robust durability required for high-ambient temperature regions.

Technical Specification Table

Attribute	Details
Model	ES7FT.4 (102G4707)
Utilisation	LBP (Low Back Pressure)
Domaine	Freezing / Deep Cooling
Cooling Wattage at - 23.3°C	147 Watts (CECOMAF)
Cubic Feet Capacity	Approx. 7 - 10 cu.ft
Liters Capacity	200 - 300 Liters
Kcal/h	126 kcal/h
Oil Type & Quantity	Polyolester (POE) / 180 cm ³

Attribute	Details
Horsepower (HP)	1/5 HP
Refrigerant Type	R134a
Power Supply	220-240V / 50Hz / 1Ph
Cooling Capacity BTU	502 BTU/h
Motor Type	RSIR (Resistance Start - Induction Run)
Displacement	5.70 cm ³
Winding Material	Copper
Pression Charge	Low Pressure Side
Capillary	0.031" or 0.8mm (application dependent)
Recommendation	Domestic Fridge, Chest Freezer, Water Dispenser
Appliance Type	
Temperature Function	-35°C to -10°C
Cooling System	Static (S)
Commercial Class	Semi-Commercial / Residential
Amperage (RLA)	1.1 A
LRA (Locked Rotor Amps)	5.4 A
Type of Relay	PTC Starter
Capacitor	N/A (RSIR Configuration)
Country of Origin	Slovakia

Efficiency Metrics (COP) & Performance Data

The efficiency of the ES7FT.4 is measured by its Coefficient of Performance (COP). Below is the performance breakdown at various evaporating temperatures (Condensing Temp at +55°C).

Evaporating Temp (°C)	Cooling Capacity (Watts)	Power Consumption (Watts)	COP (W/W)
-35	71.6	107	0.67
-30	99.5	125	0.80
-23.3 (Standard)	147	148	0.99
-20	176	160	1.10
-15	228	179	1.27
-10	290	200	1.45

Comparison with Alternative Models

When comparing the **ES7FT.4** to other popular 1/5 HP units, we see distinct differences in displacement and energy draw. For instance, the **ZMC GM70AZ** offers similar wattage but often utilizes different winding resistances. The Secop ES series is specifically “Energy Optimized,” meaning it prioritizes a lower amperage draw during the long run cycles typical of LBP freezing.

Professional Recommendations & Field Notice

As an expert in the field, I recommend the following for any technician installing the ES7FT.4:

1. **Vacuum Procedure:** Always achieve a vacuum of at least 500 microns. R134a and POE oil are highly hygroscopic; moisture will lead to acid formation and premature motor failure.
 2. **Filter Drier:** Replace the filter drier (minimum 15g-20g XH-9) every time the system is opened.
 3. **Start Components:** If the compressor fails to start in high-heat environments, ensure the PTC starter is not cracked. These units rely on a clean electrical signal to engage the start winding.
-

Compressor Replacements (Cross-Reference)

5 Direct Replacements (R134a)

- **Embraco:** EMT6170Z or EMY70HSC
- **Danfoss:** TLS7F
- **ZMC:** GL70AA
- **Tecumseh:** THG1365Y
- **Jiaxipera:** ND1111Y

5 Replacements (Alternative Gas - R600a)

Note: Requires complete system flushing and capillary adjustment.

- **Secop:** TLES7.5KK.3
 - **Embraco:** EMX70CLC
 - **ACC/Seko:** HMK80AA
 - **Donper:** L76CZ1
 - **Huayi:** HYE69Y
-

Focus Keyword: Secop ES7FT.4 Compressor 1/5 HP R134a Technical Specifications and Replacements

SEO Title: Secop ES7FT.4 Compressor | 1/5 HP | R134a | Mbsmpro.com Technical Guide

Meta Description: Detailed technical sheet for the Secop ES7FT.4 (102G4707) compressor. Includes 1/5 HP power ratings, R134a gas data, cooling capacity tables, and 10 expert replacement options for refrigeration repair.

Slug: secop-es7ft4-compressor-1-5hp-r134a-specs

Tags: Mbsmgroup, Mbsm.pro, mbsmpro.com, mbsm, Secop, ES7FT.4, 102G4707, 1/5 HP, R134a, LBP Compressor, Refrigerator Repair, EMT6170Z, TLS7F, GL70AA, THG1365Y, ND1111Y, TLES7.5KK.3

Excerpt: The Secop ES7FT.4 is a high-efficiency 1/5 HP hermetic compressor engineered for R134a LBP applications. With a displacement of 5.70 cm³ and a cooling capacity of 147W at -23.3°C, it is an ideal choice for tropical refrigeration. This guide provides full technical data, COP metrics, and professional replacement cross-references for HVAC technicians.



1/5 hp, 102G4707, EMT6170Z, ES7FT.4, GL70AA, LBP
compressor, mbsm, mbsm.pro, mbsmgroup, mbsmpro.com,
ND1111Y, R134a, Refrigerator Repair, Secop, THG1365Y, TLS7F

[mbsmpro.com-Secop ES7FT4 Compressor 15 HP R134a Technical Specifications and ReplacementsDownload](#)

Latest Articles

- [Guide de Dépannage de la Carte Inverter : Climatiseur Kolin KSM-IW20WAE](#)
- [RCFF-2HP Capillary Tube for a Samsung 18000 BTU air conditioner](#)
- [Carbon brushes washing machine motors](#)
- [Chauffe-eau Junkers : Restauration d'un Classique](#)
- [WS57H Compressor, 1/6 hp, Capacitor Requirement 4mf](#)
- [Hisense inverter expert, installtion](#)
- [Copeland D3DS5-100X 10 HP Freezer Compressor](#)
- [Bitzer 6G-30.2Y: The High-Performance 30 HP Semi-Hermetic](#)
- [Réparer un chauffe-eau à gaz Olympic 6L](#)
- [Best piping practices for semi-hermetic systems](#)
- [Core ChauffeEau Junkers Mid-1980s to Late 1990s](#)
- [Not recommended R410A to R407c](#)
- [Details of refrigerant R134a](#)
- [The electrical circuit for a timer-based steam refrigerator is an interesting one](#)
- [Changing Filter 1/5 Hp](#)
- [1/5 HP Compressor oil change: How much and how to do it right](#)
- [Deep cleaning AC units from A to Z... that's our craft](#)
- [Plumbing Fittings Explained](#)

- Can the GL80 compressor be installed in place of the GL90?
- The process of replacing the air conditioner compressor is successful, and it is working as it was before ?